


Parts Identification Guide  
PID006/0105

# CD Dryer




Models 600, 800 and 1000





CD600 / 800 / 1000 Dryer

- |                                   |                                       |
|-----------------------------------|---------------------------------------|
| 1. On/Off Rocker Switch           | 31. Process Blower Contactor          |
| 2. Emergency Push Button Stop     | 32. Control Relays                    |
| 22. Power Filter Board            | 33. Card Rack Assembly                |
| 23. Power Supply                  | 34. Heater Fuses                      |
| 24. Control Fuses                 | 35. Process Heater Contactor          |
| 25. Regeneration Blower Contactor | 36. Regeneration Heater Contactor     |
| 26. Regeneration Blower Overload  | 37. Disconnect Switch (behind cables) |
| 27. Sensor Block                  | 38. Transformer                       |
| 28. Dewpoint Sensor               | 39. Vacuum Fluorescent Display        |
| 29. Blower Fuses                  | 40. Operator Board                    |
| 30. Process Blower Overload       |                                       |



CD600 / 800 / 1000 Dryer

- 3. Process Filter
- 4. Regeneration Filter
- 5. Process Heater Box
- 6. Regeneration Heater Box
- 8. Process Blower
- 11. Bed Drive Motor
- 12. Motor Bracket
- 13. Drive Shaft
- 14. Tension Spring
- 15. Large Drive Gear
- 20. High Temperature RTD
- 21. Return Air RTD