



Parts Identification Guide

PIH006/0305



TW2 Thermolator





TW2

- | | |
|-----------------------------|--|
| 1. Transformer | 7. From Process Gauge |
| 2. Main Terminal Block | 8. Graphic Overlay w/Operator Board Underneath |
| 3. TW2 Coiled Cable - 15' | 9. Low Pressure Switch |
| 4. Mercury Contactor Heater | 10. Pump Contactor |
| 5. Motherboard | 11. Pump Overload |
| 6. To Process Gauge | |



- TW2**
- 14. Heater
 - 15. Heater Tank
 - 16. Optional Heater
 - 17. From Process Thermocouple
 - 18. Mixing Tank
 - 19. Motor Drip Cover
 - 20. Pump Motor
 - 21. To Process Check Valve (Mold Purge Option)
 - 22. To Process Connection
 - 23. From Process Connection
 - 24. Cooling Ball Valve
 - 25. Cooling Out Check Valve (Mold Purge Option)
 - 26. Cooling Out Connection
 - 27. Cooling In Connection
 - 28. Pressure Relief Valve
 - 29. Mold Purge Solenoid Valves
 - 30. Cooling Valve Actuator
 - 31. Caster Wheels